

Lessons Learned from Embankment Dam Seepage Failures

11:00-12:00 AM



Gannett Fleming




Maryland
Department of
the Environment

Dam Types


- 💧 Earth Embankment
- 💧 Rockfill
- 💧 Concrete
- 💧 Masonry
- 💧 Timber Crib
- 💧 Rubber/Inflatable
- 💧 Steel

U.S. Dams by Type



Data Source: USACE National Inventory of Dams

U.S. Dams by Decade Built





Data Source: USACE National Inventory of Dams


■ Concrete Dams

■ Embankment Dams

2 Hp Bulldozer



4 Hp Scraper



Steam Roller



Patented 1904
First earth embankment dam compacted with
sheepsfoot roller was Henshaw Dam in 1920-23
Source: Dr. David Rogers


**Earthmoving
Equipment**




August 10, 1908.

As. Olive bridge Dam, Northeast corner. Class 2. North American.


**MAIN DAM OF THE ASHOKAN RESERVOIR BROWN STA. N.Y.
200 FT. HIGH**



1940s-70s
Earthmoving
Equipment




Homogeneous Dam









Homogeneous Dam



Homogeneous Dam




Homogeneous Dam





Homogeneous Dam



Phreatic Surface

Blanket Drain


Relief Wells

Confining Clay Layer


Overburden

Bedrock


Homogeneous Dam



Homogeneous Dam




Homogeneous Dam




Puddled Clay Core Dam

1800s - ~1920



Homogeneous Dam With Cutoff Wall (~1860 – ~1930)







Figure 1-5
Typical cross section through left embankment.
(Source: 1923 Construction Drawings)






ACC - HDG.R. 101

CONTRACT 3, NOV. 19. 09.



#17 ASHOKAN RESERVOIR. Railroad on core wall, East dyke. Sep. 30th. 1909.

**UNLOADING DIRT AT SOUTH WING OF MAIN DAM
BROWN'S STATION N. Y.**






ACG HDG,

CONTRACT 60 300

Zoned Dam



Impervious Fill

Phreatic Surface


Cutoff Trench

Toe Drain

Overburden

Bedrock

Zoned Dam with Grout Curtain



Failure By Internal Erosion



01 3 21

Internal Erosion Terms

Suffosion

Heave

Blowout

Piping

Backward erosion

Scour

Sub-surface Erosion

piping

Sloughing

Hydraulic Fracture

True Piping

ASDSO Dam Piping Failure Video

Teton Dam

Clear Water Springs from Joints

June



1976

Teton Dam

June 5, 1976

Muddy Seepage Observed at Right Abutment 8:30 a.m.



Two Dozers Sent to Fill Hole, 10:30 a.m.





AFTER VAINLY TRYING TO FILL BREACH
IN EMBANKMENT OF TETON DAM,
"CAT" OPERATORS BACK TOWARD
SAFETY AS THEIR BULLDOZERS SLID
INTO THE WIDENING GAP

June 5, 1976

10:45 a.m.







11:20 a.m. Large Vortex Observed In Reservoir







Dam Crest Breaching, 11:55 a.m.






Early Afternoon





.... 14 Lives Lost

.... Over 1 Billion in Property Damage



A sign expressing feelings concerning the Teton Dam was posted next to wrecked homes in Rexburg during cleanup efforts.

Post Register
file photo

Case History: Tongue River Dam, Montana

- Constructed 1937-1939
- 1,300 feet long, 91 feet high
- 65,000 AF Storage





Tongue River Dam, Montana

Photo courtesy of Dr. Deb Miller



Void

Tongue River Dam, Montana

Photo courtesy of Dr. Deb Miller



Tongue River Dam, Montana

Photo courtesy of Dr. Deb Miller



Tongue River Dam, Montana


Photo courtesy of Dr. Deb Miller

Embankment Cracking


Casagrande (circa 1950)


Cracks are likely to occur in most embankment dams, not only in poorly constructed ones, or where topographic conditions are especially unfavorable






**Longitudinal
Crack**









2008 Wenchuan
Earthquake
Sichuan, China




Transverse Cracking








Zoned Dam with Grout Curtain



Zoned Dam with Internal Filter & Drains









Drain Gravel



Drain Sand





SLOT SPECIFICATIONS

NOMINAL PIPE SIZE: 6"
 SCHEDULE: SDR 35
 NOMINAL O.D.: _____ (I.D.: _____)
 NOMINAL WALL THICKNESS: _____
 SLOT WIDTH: .020 X slot length 1.3"
 SPACING BETWEEN SLOTS: .250
 NUMBER OF ROWS: 8
 ENDS: BELL X GASKET
13' lgt/ls.











What did we learn from Fontenelle Dam that is missing in this detail?



Zoned Dam with Internal Filter & Drains



Impervious Fill

Phreatic Surface

Cutoff Trench

Chimney Filter and Drain


Blanket Drain

Overburden


Bedrock


Grout Curtain

Zoned Dam with Berm




Zoned Dam with Upstream Slope Protection





Video Clip of Modern Earth Dam Embankment



Flow



Overburden

Foundation Rock





Three Conduit Failure Modes

- 💧 Seepage along conduit
- 💧 Seepage into the conduit
- 💧 Seepage out of conduit

Three Conduit Failure Modes

- 💧 Seepage along conduit
- 💧 Seepage into the conduit
- 💧 Seepage out of conduit











10 5'0



08/09/2008











Lake Wendy, Colorado

Sheep Creek Dam









Dr. Erwyn Freeman 01-003
Yazoo Co.



AUG 4 2004





Photo Courtesy of Jill Butler






Anti-seepage Collar →





Photo Courtesy of Jill Butler

Densely
Compacted Fill



Densely
Compacted Fill

Densely
Compacted Fill



10 27 '95





Anti-seepage Collar

No Concrete Cradle



Concrete Cradle

Anti-seepage Collar











What's the Problem?





Use of seepage cutoff collars:

Corps of Engineers (1974)

"In future designs, cutoff collars for seepage control are not to be provided for conduits through earth and rockfill dams."

NRCS (1985) for dams

"Use a filter and drainage diaphragm around any structure that extends through the embankment...." (Do not use cutoff collars.)

NRCS (1985) for ponds

"Seepage along pipes extending through the embankment shall be controlled by use of a filter and drainage diaphragm, unless it is determined that anti-seep collars will adequately serve the purpose."

USBR (1987)

"When a conduit is selected for a waterway through an earth or a rockfill embankment, cutoff collars will not be selected as the seepage control measure."



Filter Diaphragm Around Outlet Conduit

ASTM C-33 FINE AGGREGATE (SAND)
GRADATION FOR FILTER DIAPHRAGM


SIEVE SIZE	PERCENT PASSING
$\frac{3}{8}$ INCHES	100
NO. 4	95-100
NO. 10	74-94
NO. 20	35-75
NO. 30	25-60
NO. 50	10-30
NO. 100	2-10







USBR Guidelines - ACER Tech. Memo. No. 9 (1987)



- **Wide trench to allow for equipment**
- **Provide intimate contact with foundation**
- **Articulated design if settlement a concern**
- **Use a robust material for conduit (No CMP!!)**
- **Use 'Battered' sides (1:10)**
- **Use rounded top**
- **Use sloped fill (6:1) for direct compaction against sides**
- **Keep fill same level on both sides**
- **NO SEEPAGE COLLARS**
- **FILTER DIAPHRAGM**

What is wrong?







8' Diameter RCP & Outlet Structure. View Looking Upstream


Three Conduit Failure Modes

- Seepage along conduit
- Seepage into the conduit
- Seepage out of conduit







Seepage Into a Conduit




Seepage Into a Conduit




Seepage Into a Conduit




Seepage Into a Conduit




Seepage Into a Conduit




Seepage Into a Conduit



Seepage Into a Conduit



Seepage Into a Conduit





30 6 '96



Nelson Perch Pond, ND





Nelson Perch Pond, ND



Nelson Perch Pond, ND



Nelson Perch Pond, ND



Nelson Perch Pond, ND



Nelson Perch Pond, ND



Nelson Perch Pond, ND



Nelson Perch Pond, ND



King No. 1 Dam Wyoming, WY



07.21.2014 11:20

King No. 1 Dam Wyoming, WY



07.21.2014 11:32

King No. 1 Dam Wyoming, WY



07.21.2014 11:34



21.2014 11:32

Three Conduit Failure Modes

- Seepage along conduit
- Seepage into the conduit
- Seepage out of conduit












Seepage Out of a Conduit




Seepage Out of a Conduit



Seepage Out of a Conduit



Seepage Out of a Conduit





















Animal Burrows/Piping




Rodent Activity






Muskrat



dam crest




Beaver



Groundhog

crest



phreatic surface



~30-Foot Long Groundhog
Tunnel at Spruce Run Dam

Used Smoke Bomb and
Probe to Locate Tunnel

Photo Courtesy of Marc
Brooks, NJWSA

Burrowing Beaver Contributes to Dam Collapse

The northeast Texas community of Edgewood received rain for a few days leading up to Thursday, March 12, 2009. That morning, rain fell again on the already damp town, and by 12:45 p.m. an earthen dam on the 25-acre private lake south of town had failed. A beaver had tunneled into the 14-foot-high earthen dam, contributing to the dam's collapse.

Water rushed through the southern parts of Edgewood, rising in lawns. The Edgewood Volunteer Fire Department reacted quickly, closing flooded FM 859. School buses were re-routed. Later, as the floodwaters receded, people were relieved to discover that no one was hurt and there was no significant property damage. The community was fortunate despite the dam's failure.

"We were scheduled to do an inspection there the following week," says Warren Samuelson, manager of the TCEQ's Dam Safety Program. "The dam's owner had seen water flowing through the dam but didn't completely understand the nature of the problem."

Texas has experienced dam failures in the past 20 years, according to Samuelson. In 2008, one dam



Rodent Hole Suspected Cause of Dam Failure in Garfield County

An irrigation dam in Garfield County failed on June 23, 2002. The dam was located on Taylor Creek approximately 22 miles southeast of Jordan, Montana. The estimated capacity of the dam when filled to the emergency spillway crest was 1,000 acre-feet. The height of the dam was approximately 32 feet.

Flash flood warnings had been issued the previous night, with a total of 3 to 5 inches of rainfall expected in Garfield County. At 6:00 a.m. on Sunday June 23, the dam owner went to see how much water had accumulated in the large reservoir. When he arrived, water was running through the emergency spillway and leaking through a gopher hole on the embankment (near the top portion). The owner promptly called all of his downstream neighbors.

The water created a larger leak through this area and by 9:00 a.m. breached the embankment. There was no evidence of dam overtopping.

Fortunately, downstream



Taylor Creek Dam Failure - Photo by Candace Linder, NRCS

damage was minimal. Several gravel roads were washed out. Damage also occurred to a bridge on U.S. Highway 200. The basement of one house downstream was flooded. The dam failure also reportedly caused downstream stock dams to break.

(Source: National Weather Service Report, Glasgow, Montana, U.S. Natural Resources and Conservation Service Engineering Trip Report, Glasgow, Montana)



Edgewood Old City Lake Dam, TX
Partial failure in 1988, failed in 2009 – both due to animal burrows
Owner had removed 20-30 beaver in past few years

Troublesome muskrat causes levee to fail in Missouri town





Anthony Souffle/AP Photo. [Enlarge photo.](#)


Water pours through a break in the Pin Oak levee Friday in Winfield, Mo. A new defense is in the works: a quickly constructed 4-foot-tall sandbag levee to protect 100 homes in the floodwater's path.

Failure From Deterioration & Animal Damage









Posted March 21, 2008 - 10:00pm

Truckee Canal at Fernley Nevada

Rodent burrows blamed in canal failure



Damages estimated to be ~\$50,000,000



Truckee Canal Breach – Source: USBR Investigative Evaluation Report March 2008



Truckee Canal Breach – Source: USBR Investigative Evaluation Report



Truckee Canal Breach – Source: USBR Investigative Evaluation Report

Santa Clara Dam Failure, Santa Clara

Sept. 11, 2012





KSL STUDIO

WASHINGTON COUNTY



66°
10:00



KSL NEWS 10

Santa Clara Dam Failure, Santa Clara Utah, Sept. 11, 2012



15 Minute Break

Lessons Learned from Embankment Dam Seepage Failures

11:00-12:00 AM



Gannett Fleming



Maryland
Department of
the Environment