

Lessons Learned from Spillway Failures

12:45-1:45 PM




Causes of Dam Incidents

<u>Fundamental Causes</u>	<u>Percentage</u>
Sabotage	0
Earthquake Instability	1
Faulty Construction	2
Gate Failure	2
Sliding	10
Deformation	11
Spillway Erosion/Breach	14
Overtopping	25
Seepage/Piping	35



Failure Incident Types



US Deaths From Dam Failures

Dam Failure

Lives Lost

South Fork, PA (1889) 2,209

No known deaths attributed to a spillway breach

Austin, PA (1911) 80

Laurel Run, PA (1977) 40

Kelly Barnes, GA (1977) 39

Canyon Lake, SD (1972) 33

Teton, ID (1976) 14

Swift, MT (1964) 19

Ka Loko, HI (2006) 8

Categories of Spillway Incidents

- Inadequate Spillway Capacity
- Failure of Flow Surfaces
 - Erosion
 - Abrasion
 - Cavitation
- Structural Failure from Uplift
 - Seepage
 - Stagnation Pressures
- Structural Failure from Dynamic Loadings
- Failure of Operating Provisions
 - Hoists, Gates ...
 - Controls



1997, Flow~160,000 cfs





COURTESY: BETH BELLO





1997, Flow~160,000 cfs






Preliminary Factors Potentially Contributing to Failure

- 💧 Lack of waterstops in slab joints
- 💧 Concrete cracking and surface deterioration
- 💧 Plugging and collapse of underdrain pipes (roots)
- 💧 Unfiltered drains
- 💧 Soil-like erodible foundation in places
- 💧 Drought impacts on foundation materials
- 💧 Insufficient anchorage
- 💧 Large variations in slab thickness
- 💧 Limited slab reinforcement and joint restraint
- 💧 Cavitation?

Stagnation Pressure

- ▶ Significant damage has occurred on several Reclamation spillways



Flow Pattern Over Displacement









09.19.2011



09.19.2011



05.01.2013







05.29.2013









Water Head Needed to Lift 8" Concrete Slab:

$$= \frac{8'' \times 150 \text{ pcf}}{62.6 \text{ pcf}} = 19.2'' = 1.6 \text{ Feet}$$



2009, 20-25 gpm

Large orange graffiti tags on a concrete wall, including a stylized 'Q' with a sunburst above it. Below the tags, the text 'CNY' and 'LNY' is visible, with a peace symbol between them.

PLEASE DON'T TOUCH
JK

What would
JK

2009



2009



07/21/2009







Mount Carmel Dam, ND



Mount Carmel Dam, ND



BA12 - Auxillary Spillway - Soil Cement - July 1974



BA12 - August 20, 2007

Bad Axe Dam, Wisconsin



2007/08/20

Bad Axe Dam, Wisconsin



2007/08/20

Bad Axe Dam, Wisconsin



Big Sandy Spillway, WY Stagnation Pressure Failure



Slab Failed in 1983
After 30 years of Operation





Dye Injected


Dye Observed
Exiting

























Hope Mills Dam , NC (2010)





Big Sandy Spillway, WY Stagnation Pressure Failure



Foundation Erosion



Slab Failed in 1983
After 30 years of Operation

Dutch Fork Lake, Washington County, PA





Fellows Lake Dam, Greene County MO (Photos courtesy of Glenn Lloyd)







Old sealant between
concrete expansion joints
needs to be removed and
replaced.





7 28 '01





KOBELCO

WATER





12 27 '01

Rounded Top of Joint Filled with Flexible Sealant and 3/4" Offset

Smooth Dowels

Waterstop

Concrete Key

Continuous Bottom Reinforcement

Leveling Concrete on Bedrock









Woodlake Dam (Moore County), Post Hurricane Matthew (2016)




Silver Lake Dam Failure, Michigan








Silver Lake Dam, Mi


- Constructed 1896, rebuilt 1912 & 1945
- 30.5' high, 1,500' long embankment, 23.6 mi²
- Four earth saddle dikes
- Upgrades Completed 2002
- Increase spillway capacity (PMF)
- **Fuse plug** emergency spillway (Dike 2)
- Also raised dam crest
- **Un-manned site**



































- 5-10 year flood event on May 14, 2003
- Fuse plug activated
- Spillway channel eroded well below fuse plug foundation
- Fuse plug 9" below service spillway crest
- Fuse plug foundation and channel susceptible to erosion
- Fuse plug flows 5,000 → 30,000 cfs ~PMF



Summary of Project Structure Elevations



25'

Final Eroded Fuse Plug Breach



- Flooding caused >\$100 million damages
- 1,700 people evacuated
- Several bridges damaged or washed out
- Tourist Park Dam overtopped and failed
- Power plant flooded and shut down
- No loss of life or personal injuries (EAP)





Flooding caused over \$100 million in damages, but no fatalities

Failure By Spillway Erosion



> 27,000 Earth-cut Emergency Spillways In the U.S.

Niagara Falls



1842-1905 Average Rate of Erosion =
3.8 feet per year (240 feet in 63 years)

Federally Owned or Regulated Dams



27,252 Dams



2,700 Dams




2,524 Dams



669 Dams



49 Dams



Earth Cut Auxiliary Spillway

Auxiliary
Spillway





United States
Department of
Agriculture



Natural
Resources
Conservation
Service

Conservation
Engineering
Division

July 2005

Earth Dams and Reservoirs

TR-60


United States
Department of
Agriculture

Natural
Resources
Conservation
Service

Part 628 Dams
National Engineering Handbook

Chapter 50

Earth Spillway Design





Spillway Training Dike



Pohick No. 4, Fairfax VA



Pohick No. 4, Fairfax VA



Earthen spillway scour/erosion



Earthen spillway scour/erosion



VEGETAL EROSION PROTECTION





Figure 50-4 Spillway gully resulting in breach of spillway





Old Timbers Dam, Big Oaks NWR, Indiana



28. Erosion gully in downstream channel of emergency spillway, looking upstream.
Old Timbers Dam, Big Oaks NWR, Indiana










Breach

Black Creek, Mississippi

Flow Duration - 23 hr

Max Depth – 5.1 feet

Spillway Width – 100 feet



Slide By: **Darrel M. Temple, P.E.** - USDA Agricultural Research Service

Three Phase Approach



Photos courtesy of Darrell Temple



PM
JUN. 29 1989

Black Creek Dam, Mississippi

Flow Duration - 23 hr

Max Depth - 5.1 feet


Spillway Width - 100 feet

~190,000 CY Eroded





Slide By: **Darrel M. Temple, P.E.** - USDA Agricultural Research Service

~190,000 CY Eroded



~190,000 CY Eroded





90'±

23,750 Dump Trucks



(Assumes 8cy per load)

LaMoure Dam, ND (2009 Flood)



e, ND
: N 46° 17.75' / Longitude: W 098° 15.50'
Dam

























Dam failure drains Fairfax County lake, kills wildlife


By Derek Kravitz

Tuesday, October 5, 2010; 11:38 PM

During the heavy rains that drenched the Washington region Thursday, Kingstowne Park dam in Fairfax County's Alexandria section failed. It was a quick and quiet death,

The Fairfax County Park Authority and the Board of Supervisors acquired the Kingstowne Lakes in 2002 from the original developer, said James W. Patteson, Fairfax's director of public works and environmental services, and planned to conserve the area





**No known fatalities from
spillway breaching**

**Sugar Creek Dam L-44, Caddo County Oklahoma
Tropical Depression Erin (Aug. 18-19, 2007)
>8" in less than 12 hours**













Flow

Photo Courtesy of Ed Fiegle



Photo Courtesy of Darrel Temple



Mills Creek Dam, VA



Spillway Crest

Major discontinuities concentrate the flow where there is no vegetal cover and/or the surface is disturbed.



OCT. 17. 2001
AM 8:31





Local Scour






Figure 1.2 Schematic Representation of Local Scour at a Cylindrical Pier (Richardson et al., 2001)



(a) Top View




(b) 3-D View





SURFACE DISCONTINUITIES





Slide Courtesy of Gregg Huddock, Golder Associates



Spillway Erosion Assessment



S
I
T
E
S

2005.1


Water Resources Site Analysis Program




**Spillway
Breached (27%)**



**Minor
Damage
5%**








Significant Damage (39%)



Spillway Almost Breached (29%)




Spillway Breached (27%)



Souhegan 15


Souhegan 15, NH

 Souhegan Site 15




08/19/2015

Aux. Spillway Erosion



AUX. SPILLWAY: Crest = 833.00, BW = 45.
 WS = 1, STR = 1, FILE = Souhegan15_24HR

Material Description	Detach. Rate (ft/h)/(lb/sq ft)	Dry Density (lbs/cu ft)	Headcut Index (Kh)	Percent Clay	Plasticity Index	Rep. Diameter (in)
Topsoil	--	100.	0.28	15.0	5.	0.00200
SM	--	115.	0.08	10.0	5.	0.04700
SM & CL	--	110.	0.07	20.0	15.	0.00400



FLOW →

WATER SEEP

LEVEL SECTION
EL 833.0

PROFILE ALONG ϕ OF EMERGENCY SPILLWAY

page 92
const. book

860
850
840
830
820

3+00 4+00 5+00 6+00 7+00

TP-205 EL. 839.0 27' LEFT OF ϕ

TP-201 EL. 837.6 3' RIGHT

TP-203 EL. 853.8 33' RIGHT

TP-205 EL. 849.0 60' RIGHT

TP-206 EL. 831.4 28' RIGHT

TOPSOIL, STONY, 10'
8.0' SM-CL
SILTY FINE SAND
AND CLAY.
8.0' SM
SAND, SILTY,
MOIST, MED.
TO HARD,
GLACIAL TILL.

10' TOPSOIL
9.0' SM,
SILTY SAND,
DENSE.
GLACIAL TILL
9.0' SM-SM
SILTY SAND TO
SILTY GRAVEL, TILL.
SM, SILTY SAND,
STONY, GLACIAL
TILL.

10' TOPSOIL, STONY.
ORIGINAL
GROUND
LINE
24.0' SM,
SILTY SAND,
MOIST, HARD
TO VERY HARD,
GLACIAL TILL.

10' TOPSOIL, STONY.
11.0' SM,
SILTY SAND,
W/SCAGGLES,
MOIST, HARD
TO DENSE,
GLACIAL TILL.

2.0' SM, SILTY
SAND, GRAVELLY.
5.0' SM-CL
SILTY TO
CLAYEY SAND,
SOME STRINGS
GLACIAL TILL.

0.5' TOPSOIL, MIX W/STONES.
3.0' SM, SILTY SAND,
W/HR GLACIAL TILL.
4.5' SM-CL
SILTY SAND &
SILTY CLAY, MOIST.
SM, SILTY SAND
W FRAGMENTS
OF LIME SHIST,
GLACIAL TILL.

S=0.8

S=0.8

60'

The two remaining test pits were at the foot of the slope and showed 4.-5.' of silty sand underlain by 5.' of horizontal interbedded layers. An additional 2.' of silty sand was found below the interbedded SM-CL in one of the pits. No bedrock or unconsolidated materials were found in any of the test pits.

The bottom of the spillway excavation will be in compact silty sand material.

Alternate Emergency Spillway

Alternate Emergency Spillway

Three holes were used to investigate the Alternate Emergency Spillway which is located in the vicinity of the left abutment.

All three holes show 1.5-3.0' of relatively coarse silty sand underlain by weathered gneiss or schist which becomes sound bedrock at about 2.0'.

The watertable along the centerline of the proposed outlet structure was about 2.0' below ground level. Recharge is estimated to be medium.

The pocket penetrometer reading for the centerline portion of the interbedded SM and CL was about 3 tons per square foot. The SM materials are firm to dens.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE


DRAWING NO.

SHEET 4 OF ____


DATE _____

CONSTRUCTION DETAILS

1. THE EXCAVATION LIMITS ARE APPROXIMATE AND WILL BE ADJUSTED IN ACCORDANCE WITH CONDITIONS ENCOUNTERED.
2. ROCK EXPOSED IN THE BOTTOM OF THE CUTOFF TRENCH SHALL BE THOROUGHLY CLEANED AND SHALL BE INSPECTED BY THE ENGINEER PRIOR TO THE PLACEMENT OF COMPACTED FILL MATERIAL.



PLAN OF CUTOFF TRENCH



PROFILE ALONG C OF DAM AND CUTOFF TRENCH

"AS BUILT"


PROFILE ALONG C OF EMERGENCY SPILLWAY AS BUILT

STONY CREEK SITE No. 9
 STONY CREEK WATERSHED
 SHENANDOAH COUNTY, VA.
 DETAILS OF CUTOFF TRENCH


U. S. DEPARTMENT OF AGRICULTURE
 SOIL CONSERVATION SERVICE

Prepared by R.E. CURTISS	Date 2/77	Approved by J.F. BLODGETT	Date 2/77
Drawn by 5	Checked by 22	Project No. VA-588-P	

DEC 21 1977




PLAN




SECTION A-A

TYPICAL SPILLWAY CONSTRUCTED IN CLASS II ROCK



SECTION A - A


ROCK SURFACE DIRECTS GULLYING OF OVERBURDEN TOWARD EMBANKMENT TOE



SECTION A - A

ROCK SURFACE DIRECTS GULLYING OF OVERBURDEN TOWARD EMBANKMENT TOE


South Fork 17, WV



South Branch Potomac 17



Bedrock Dipping
Towards Dam









Flow











6 13 '00

White Oak Dam

Location: Madison County, VA

Dam Height: 63 Feet

Spillway Width: 75 Feet

Date: June 27, 1995

Event: 24" Rain in 18 Hrs

Maximum Head: 10 Feet

Max. Discharge: 7,000 cfs





White Oak Dam

Eroded: 10,500 C.Y.

Headcut Depth: 40 Feet

Headcut Length: 400 Feet





10 16 '97



01 1100

Auxiliary Spillway Discharge Channel
Before Activation of Spillway



Photo Courtesy of Thomas I Roberts, VADCR

Auxiliary Spillway Discharge Channel After Activation of Spillway




Photo Courtesy of Thomas I Roberts, VADCR

Sugar Creek Dam L-44, Caddo County Oklahoma

Tropical Depression Erin (Aug. 18-19, 2007)

>8" in less than 12 hours













Flow

Photo Courtesy of Ed Fiegle



Photo Courtesy of Darrel Temple

El Guapo Dam, Venezuela
Failed December 16, 1999



El Guapo Dam, Venezuela
Failed December 16, 1999



El Guapo Dam, Venezuela
Failed December 16, 1999



El Guapo Dam, Venezuela
Failed December 16, 1999



El Guapo Dam, Venezuela
Failed December 16, 1999





Break

Lessons Learned from Spillway Erosion Failures

12:45-1:45 PM

