

Lessons Learned from Concrete Dam Failures

2:00-3:00 PM




Gannett Fleming



Maryland
Department of
the Environment

U.S. Dams by Type



Gravity Spillways



Gravity dams are designed so that each section of the dam is stable, independent of any other dam section






US Deaths From Dam Failures

<u>Dam Failure</u>	<u>Lives Lost</u>
South Fork, PA (1889)	2,209
St. Francis, CA (1928)	450
Walnut Grove, AZ (1890)	150
Mill River, MA (1874)	143
Buffalo Creek, WV (1972)	125
Austin, PA (1911)	80
Laurel Run, PA (1977)	40
Kelly Barnes, GA (1977)	39
Canyon Lake, SD (1972)	33
Teton, ID (1976)	14
Swift, MT (1964)	19
Ka Loko, HI (2006)	8


US Deaths From Dam Failures

<u>Dam Failure</u>	<u>Lives Lost</u>
South Fork, PA (1889)	2,209
St. Francis, CA (1928)	450
Walnut Grove, AZ (1890)	150
Mill River, MA (1874)	143
Buffalo Creek, WV (1972)	125
Austin, PA (1911)	80
Laurel Run, PA (1977)	40
Kelly Barnes, GA (1977)	39
Canyon Lake, SD (1972)	33
Teton, ID (1976)	14
Swift, MT (1964)	19
Ka Loko, HI (2006)	8

Failures By Dam Type



U.S. Dams by Decade Built



Data Source: USACE National Inventory of Dams


■ Concrete Dams

■ Embankment Dams

Dam Type Comparison

Concrete Gravity Dam Limitations:

1. High Seepage Gradient
2. Best on Shallow/Sound Rock Foundations



Concrete Gravity Dam Advantages:

- 1) Smaller Material Volume
- 2) Smaller Foundation Footprint
- 3) Integrated Spillway / Outlet Works
- 4) Better Withstands Overtopping
- 5) More Easily Facilitates Future Raise

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010



Furens Dam
St. Etienne, France
Built 1858-66

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Stone Masonry

Furens Dam
St. Etienne, France
Built 1858-66

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Stone Masonry



**Sodom Dam
New York, NY
Built 1888-93**

Image Source: The Design and Construction of Dams, E. Wegmann

Gill Eng. Co. NY

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Stone Masonry

**Sodom Dam
New York, NY
Built 1888-93**



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Cyclopean Concrete



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Cyclopean Concrete



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Cyclopean Concrete



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Reinforced Concrete

**Big Bear Valley Dam
San Bernardino, CA
Built 1911**

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Reinforced Concrete

**Warrior Ridge Dam
Huntington, PA
Built 1905-07**

**Ambursen
Hollow-Type Dam**

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Reinforced Concrete

Gem Lake Dam
Bishop, CA
Built 1915-16

Max. Height: 80 feet

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Conventional Mass Concrete



Shasta Dam
Shasta Lake City, CA
Built 1938-45

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970


1980

1990

2000

2010

Conventional Mass Concrete



**Shasta Dam
Shasta Lake City, CA
Built 1938-45**

1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980


1990

2000

2010

Conventional Mass Concrete

Water Pipes For Thermal Cooling



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000

2010

Roller-Compacted
Concrete (RCC)

Willow Creek Dam
Heppner, OR
Built 1981-83

1860 1870 1880 1890 1900 1910 1920 1930 1940 1950 1960 1970 1980 1990 2000 2010

**Roller-Compacted
Concrete (RCC)**

Spreading



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980


1990

2000

2010

Compaction

**Roller-Compacted
Concrete (RCC)**



1860

1870

1880

1890

1900

1910

1920

1930

1940

1950

1960

1970

1980

1990

2000


2010

**Roller-Compacted
Concrete (RCC)**




Olivenhain Dam, CA

Construction Practice Timeline



Histogram of US Dam Construction (1800-2004) for
 Dams Listed as Concrete, Gravity, Buttress, Arch, Multiple Arch, Masonry or
 Dams Listed as having a Controlled Spillway



Notes: 1) Source of Data - National Inventory of Dams, USACE, 79777 Dams Total
 2) Does not include 9500 dams where the year construction completed is not reported or invalid
 3) Total Number of Dams (not including 9500 with unreported/invalid data) = 8178

Courtesy: Dr. Donald Bruce, Geosystems, L.P.

Spillway Capacity




Occoquan Dam, VA




Spillway Capacity

Occoquan Dam, VA


Typical Cross-Section




Typical Cross-Section




Sliding Failure Mode



Overturning Failure Mode



Critical Potential Failure Planes



“When a big project has troubles,
they may well be big troubles.”

John Lowe III

Consulting Engineer

(Referring to Tarbella Dam - 1982)

**NOTEWORTHY
GRAVITY DAM FAILURES**



Stone Masonry Gravity Dam

Built: 1878-1880

Partial Failure: 12:00 PM, March 14, 1884


Complete Failure: 5:45 AM, April 27, 1895

Fatalities: 85

BOUZEY DAM

EPINAL, FRANCE

Bouzey Dam Epinal, France



Bouzey Dam Epinal, France

Overturning Failure 1895, Loss of Life = 85 people



Edition J. Armand, Epinal


Cliché Groshens

BOUZEY. - La Digue après la rupture (27 avril 1895)


Image Source: Cassier's Magazine, November 1896

Looking Toward Left Abutment

Bouzey Dam
Epinal, France



88. - ÉPINAL. - Étang et Digue de Bouzey



Galeries Réunies de l'Est, Épinal



Stone Masonry Gravity Dam

Built: 1890-93

Failed: 11:20 AM, April 7, 1900

Fatalities: 8 (At Powerhouse)

AUSTIN DAM

AUSTIN, TX



Image Source: USGS Paper No. 40, 1900

February 1893

Max. Height: 66 feet







Image Source: USGS Paper No. 40, 1900

B. LIMESTONE STRATA AT HEAD GATE.

COLORADO RIVER DAM.






Flood-Induced Failure
Peak Spillway Head: 11.07 ft

A. VIEW THREE MINUTES AFTER FAILURE OF DAM.

A—B and B—C are portions of dam first broken; H—A is eastern part of dam (83 feet long on crest) left standing.




B. VIEW TEN MINUTES AFTER FAILURE OF DAM.

D'—B' is broken portion of dam still standing; B'—C' is western portion of break; C is end of western part of dam (456 feet long on crest) left standing.

Austin Dam
Austin, TX

One hour after failure





1. BROKEN DAM, SHOWING IN FOREGROUND SAND BAR LEFT IN MAIN CHANNEL.

April 1900
Austin Dam
Austin, TX





Concrete Slab and Buttress Dam

Built: 1907-08


Piping Incident: January 7, 1909



Fatalities: 0




ASHLEY DAM

PITTSFIELD, MA

Ashley Dam
Pittsfield, MA - 1909







Ashley Dam
Pittsfield, MA - 1909



Cyclopean Concrete Gravity Dam

Constructed: May - December 1, 1909

Partial Failure: January 23, 1910

Complete Failure: 2:20 PM, September 30, 1911

Fatalities: 78

BAYLESS DAM

AUSTIN, PA




Image Source:
Some Features of the Construction
and Failure of the Austin, PA, Dam
T. Chalkley Hatton, Sep 19, 1912

Max. Height: 50 feet





Figure 4. Prefailure cross section of Austin Dam at Block "D."

Key Design Features

1. Neglected Uplift Pressure
2. Embankment to Reduce Hydrostatic Load
3. Vertical Rods for Overturning Stability
4. Key Wall for Sliding Stability
5. 2-in. Dia. Boreholes on 15-20-foot Centers
6. 25-45-foot Monoliths with Keyways
7. Concrete Mix – 1.25 Barrels Cement per CY
8. Each Cement Delivery Tested
9. Outlet Works – 36-inch dia. Pipe
10. Spillway Crest Raised 2 feet




Design Engr.
T. Chalkley Hatton

Project Objectives

1. 200,000,000 Gallon Reservoir
2. \$85,000 Budget

Image Source:
Some Features of the Construction and Failure of the Austin, PA, Dam
T. Chalkley Hatton, Sep 19, 1912



Cutoff Wall Trench

January 21, 1910

Gayless Dam Austin, Pa.

Bayless Dam, Austin, PA
January 23, 1910
Max. Horizontal Displacement:
Crest: 31 inches
Base: 18 inches





Image Source: The Concrete Dam in Freeman's Run, Austin, PA., Frank P. McKibben, January 1912




Image Source: Potter County Historical Society

Why Re-fill Reservoir?

- Bayless Paper Mill major employer.
- Belief – No severe consequences from failure.
- No active independent governing influence.

Bayless Paper Mill





BAYLESS PAPER MILL

Sunny Day Failure




Bayless Dam



TO MATCH THIS
VIEW 48. SEE 49.

AUSTIN, PA. BEFORE THE FLOOD. THIS VIEW SHOWS PART DESTROYED.




Bayless Dam



VIEW NO 49, SEE 48 SAME POINT. BEFORE FLOOD.
AUSTIN, PA. AFTER FLOOD. 1911, SEE VIEW NO 48. FROM THIS POINT,
LOOKING UP THE VALLEY, SHOWING WHERE VILLAGE STOOD.

Loss of Life = 78 people

September 1911
Bayless Dam
Austin, PA





**Design Engr.
T. Chalckley Hatton**

“The failure of this dam was not the result of poor workmanship, but poor judgment upon my part. I should have sought the advice of a man more skilled than I in determining foundations for dams. Had there been such a state officer it might have resulted in saving this dam and my reputation.”



**Design Engr.
T. Chalkley Hatton**

“I was also influenced in my judgment by the necessity for keeping the expenditure within certain limits. I have since felt that a very grave responsibility for my failure to advise the client early in my engagement that no paring down of this work should be countenanced. Had I done so, either the dam would not have been built, or it would have been built in accordance with my first design. The owner had not intention at any time of building a dam the safety of which he doubted, and nn blame can be attached to him for its failure. He depended upon my judgment entirely, even though he may have tried to influence me to keep the expenditures down to the lowest possible limit”



**Design Engr.
T. Chalkley Hatton**

“To the young engineer who is called upon to design an important structure, the safety or sufficiency of which he is not entirely satisfied with, I would strongly urge the wisdom of calling to his help the advice of an older engineer skilled in that particular line. **Never sacrifice for cost, no matter how urgent your client may become.** He does not realize the danger, and you should. If you cannot agree with him, resign your engagement, for sooner or later the reckoning will come”

Source: Chalkley Hatton, Journal of New England Waterworks Assn., 1912



Conventional Mass Concrete Gravity Dam



Built: 1924-26

Failed: 11:57:30 PM, March 12, 1928


Fatalities: 400-450

ST. FRANCIS DAM

LOS ANGELES, CA



**Chief Engr.
William Mulholland**



Key Design Features

1. Neglected Uplift Pressure
2. Curved Alignment Gravity Dam
3. Original Height – 180 feet
4. Reservoir Volume – 32,000 Acre-feet
5. Largest of 9 Reservoirs Built 1920-26
6. 10 Drainholes within Max. Section
7. Outlet Works – 5 30-inch-dia. Pipes

**PLAN AND PROFILE
OF
ST. FRANCIS DAM**
SCALE OF FEET
0 5 10 15 20
CITY OF LOS ANGELES
DEPARTMENT OF PUBLIC SERVICE
BUREAU OF
WATER WORKS AND SUPPLY
ENGINEERING DEPARTMENT

Image Source:
Causes Leading to the Failure of St. Francis Dam, 1928
University of California Library Copy

Saint Francis Dam Failure, CA 1928

Foundation Problems ...





About 11:30 AM, March 12, 1928

Three People on Dam

Chief Engr: William Mulholland

Asst Chief Engr: Harvey Van Norman

Damkeeper: Tony Harnischfeger

Catastrophic Failure:
11:57:30 PM, March 12, 1928
Reservoir Empty:
≈ 40 Minutes

Sunny Day Failure




March 1928
St. Francis Dam
Los Angeles, CA





Image Source: University of California Libraries



- 205 Feet High, Foundation Failure
- Collapsed Without Warning, 11:45 p.m.
- 125-foot High Flood Wave





Image Source: Santa Clarita Valley Historical Society

Powerhouse No. 2 1.5 Miles Downstream of Dam






Image Source: US Geological Survey

**Powerhouse No. 2
Went offline at 12:02:30 AM
64 Fatalities**

**Maximum Floodwave Depth:
≈ 110 feet**



3 hours after the failure, the wave struck the town of Santa Paula, 38 miles downstream of the dam ...



Piano Keyboard

Loss of life ~390

> 50 Miles of Destruction



Loss of life ~450



As the flood approached Santa Paula in the darkness of night, two Santa Paula police officers road motorcycles through the low lying areas of town, warning residents to evacuate. Telephone operators similarly called residents through the night. This sculpture was commissioned by the Santa Paula Historical Society to commemorate these lifesaving efforts.



Roller-Compacted Concrete Gravity Dam


Completed: 2002

Failed: June 17, 2004

Fatalities: 5

CAMARA DAM

PARAIBA, BRAZIL



Camera Dam, Brazil

- RCC Dam Constructed 2002
- Failed July 17, 2004 during flood
- 5 fatalities


Camera Dam, Brazil



18 16:25



Camara Dam, Brazil



18 6 2004

Camara Dam, Brazil



Approximately 70 percent of concrete dam failures can be attributed to geological or geotechnical problems.

ICOLD, 1974



Ambursen Dam




Constructed: 1913

Failure: 1914, 6 Months After Reservoir Impoundment

Fatalities: 0

STONY RIVER DAM NEAR PETERSBURG, WV

Stony River Dam Near Petersburg, WV



51 Feet High

Stony River Dam Near Petersburg, WV



Gleno Dam Italy:

Cause: Poor workmanship and construction materials
Failed December 1923 (First filling)
356 Fatalities



Gleno Dam Italy: Cause: Poor workmanship and construction materials
Failed December 1923 (First filling)
356 Fatalities



The concrete in the arches was of a poor quality and it was reinforced with anti-grenade scrap netting that had been used during World War I. There were also indications that the dam was poorly joined with its foundation. Additionally, the concrete was believed to not be completely cured when the reservoir was filling. Reportedly, workers who complained about the construction techniques were fired.





Decommissioning Lower Lake Gerard Dam



Decommissioning Lower Lake Gerard Dam

Case Study: Roanoke Rapids Dam, NC



An aerial photograph of a dam structure crossing a river. The dam is a long, low wall with a series of vertical supports. A yellow dashed rectangle highlights a section of the dam, and within it, a yellow oval highlights a specific area. A yellow line connects the text to the highlighted area. The surrounding landscape is a mix of green forest and brownish, cleared areas.

Several indicators of changes in structural behavior in one area




ROARING LANES
POWER STATION











Underwater Inspection and Video

09/08/06


12:13:05 PM





09/08/06

12:13:05 PM





Alkali-Silica Reaction (ASR) Gel



ASR Gel



Ettringite



Movement



Engineers were tipped to a possible problem Tuesday when they noticed a slight bowing of a concrete curb on the dam deck. They also noticed that the affected

The heightened alert at the dam comes after divers Thursday discovered a crack in one of the dam's concrete support piers that measures 2 inches wide by 65 feet long.

The PUD will draw the reservoir behind the dam down another 14 feet by Tuesday for a total expected drawdown of 20 feet, Stredwick said.

Wanapum Dam,
Columbia River near Vantage, Washington



Wanapum Dam,
Columbia River near Vantage, Washington



**Incident occurred after 50
years of service!**

Wanapum Dam,
Columbia River near Vantage, Washington





← Direction of Flow


→ Downstream Deflection at Pier 4

→ Upstream Curb

Spillway Bridge Deck

27/02/2014

Wanapum Dam





Reinforced Concrete Dam

Completed: 1977

Failed: September 21, 1999


Fatalities: 0

SHIH KANG DAM, TAIWAN

75' High, 1100' long, 18 gates




Before Earthquake



No known concrete gravity dam failures related to earthquakes!

Shih Kang Dam, Taiwan, Sept. 21, 1999

Height = 70 Feet
Length = 1,170 Feet
18 Tainter Gates



Shih Kang Dam, Taiwan, Sept. 21, 1999




ORIGINAL
ELEVATION
OF DAM

APPROX. 9.25 m

- **No concrete dams are known to have failed due to earthquake loading**
- There have been some near misses (*Koyna Dam, India, M6.5; Pacoima Dam, CA, M6.8*)
- Landslides have been triggered by earthquakes
- It is not difficult to envision sliding failure modes triggered by an earthquake

Source: Gregg A. Scott, USBR PFMA Concrete Dam Failures

Foundation Improvement Options



Gallery and Drainage System



**Foundation
Drains**

**Face
Drains**

Drainhole Pressure Testing





**Calcium
Carbonate
Deposits**

Flushing Clogged Drainholes

08.20.2008




**Re-Drilling
Drainholes**



**Re-Drilling
Drainholes**

Drain Curtains

No Drainage Gallery







Structure Improvement Options

- **Post-Tensioned Rock Anchors**
- **Concrete Buttresses**
- **Geomembrane Sealing Systems**

Structure Improvement Options




Structure Improvement Options



Loch Raven Dam, Baltimore, MD





Anchor Head

Bonding Zone

Post-Tensioned Rock Anchors


Rock Anchor Head



2003.01.30

Rock Anchor Tensioning





**Roller-Compacted Concrete w/
Conventional Concrete Facing**

RCC Buttress



2004.09.05

A large concrete dam with a curved spillway. The dam is surrounded by a dense forest of green trees. The sky is overcast. The dam's surface is made of large, light-colored concrete blocks. A metal railing runs along the top of the dam. The water behind the dam is a brownish color. The foreground shows a grassy area with some green fabric or tarp.

LOCH RAVEN DAM


1914

1922

2005

Gilboa Dam Spillway, NY





Vertical Rock Anchors

58 Strand Anchors



Inclined Rock Anchors






Drainage Gallery



Erosion at toe of Gravity Spillway (2011)



09.19.2011






05.01.2013



05.29.2013



Structure Improvement Options





APR 24 2003



APR 30 2003



Lost Creek Dam, OR

**Exposed
Geomembrane
with
Fully Drained
Interior Face**



**Drainage
System**



PROF
72

72

MAY 7 2003

Multiple-Arch Dam



Lost Creek Dam, OR



Before



After

Animal Activity





QUESTIONS ?



Lessons Learned from Concrete Dam Failures

2:00-3:00 PM



Gannett Fleming



Maryland
Department of
the Environment