

MARYLAND DEPARTMENT OF THE ENVIRONMENT

Land Management Administration • Land Restoration Program

1800 Washington Boulevard • Suite 625 • Baltimore Maryland 21230-1719

410-537-3440 • 800-633-6101 • www.mde.state.md.us

STANSBURY PARK MONITORING RESULTS

Parameters	Pond #1	Pond #2	Pond#3	Sed #1 SP-S1	Sed #2 SP- S2	Sed #3 SP-S3
Total (mg/L)					Mg/Kg	
Arsenic(0.01)(3)	<0.05	<0.05	<0.05	0.160	0.056	<0.05
Chromium(0.1)	<0.05	<0.05	<0.05	1.65	17.73	.660
Cr (+6)*(0.035)(6.3)	<0.0002	<0.0002	<0.0002	1.17	5.58	4.39
Lead(0.015)(800)	<0.05	<0.05	<0.05	0.745	0.534	<0.05
Vanadium(0.0086)(580)	<0.1	<0.1	<0.1	<0.1	<0.1	<0.1

Comments

Water sample reported in mg/L

Sediment samples reported in mg/Kg

Parameters	MW #1	MW #2	MW #3	MW #4
Total (mg/L)				
Arsenic	<0.05	0.216	<0.05	<0.05
Chromium	<0.05	<0.05	<0.05	0.29
Cr (+6)*	0.00695	<0.0002	0.00117	0.03920
Lead	<0.05	<0.05	<0.05	<0.05
Vanadium	<0.1	<0.1	<0.1	<0.1
Dissolved (mg/L)				
Arsenic	<0.05	0.167	<0.05	<0.05
Chromium	<0.05	<0.05	<0.05	0.05
Cr(+6)*	0.00714	<0.0002	0.0009	0.0433
Lead	<0.05	<0.05	<0.05	<0.05
Vanadium	<0.1	<0.1	<0.1	<0.1

Comments

Water sample reported in mg/l;

* All other samples except Cr 6 run on ICP MS (EPA 200.8) using drinking water reporting levels.

Sample collected by J. Siewierski
SAMPLING DATE 5/17/2022