

Part 70 Compliance Certification Report due April 1st

Your facility is currently operating under a Part 70 Operating Permit issued by the Air and Radiation Administration (ARA). This permit requires an annual Compliance Certification due by April 1 each year. To complete the compliance certification, both an ARA form and a federal Compliance Certification form are to be used. The ARA form is to be used for certifying plant-wide conditions (Section III of your Part 70 Permit) and the federal form is to be used for certifying plant-specific conditions (Section IV of your Part 70 Permit).

Regarding the federal form, please note that sections A and B of the certification form are only required to be completed once; however, sections C and D must be completed for each permit condition of each emission unit. Deviations from permit conditions must be reported on form E. Please make as many copies of form C, D, and E as necessary.

The federal form and instructions are located at:

<https://www.epa.gov/title-v-operating-permits/epa-issued-operating-permits>

The ARA form for Section III is located at:

<https://mde.maryland.gov/programs/Air/AirQualityCompliance/Pages/index.aspx>

Please ensure that your certification is received by ARA on or before April 1st. Completed forms should be mailed to:

Maryland Department of the Environment
Air and Radiation Administration
1800 Washington Boulevard, Suite 715
Baltimore MD 21230-1720
Attn: Daniel Davis, Compliance Program

Failure to meet this deadline is a violation of your Part 70 Permit.

A copy of your annual compliance certification must also be sent to the Environmental Protection Agency at the following address:

Associate Director
Office of Enforcement and Permit Review (3AP10)
U.S. EPA Region III
1650 Arch Street
Philadelphia PA 19103-2029

If you have any questions, please call your ARA contact at 410-537-3231.

Sincerely,



Pars Ramnarain, Chief
Process Compliance Division
Air and Radiation Administration