



Brownfield Master Inventory (BMI) Report - Active Sites, By County
July 02, 2018

Howard

BMI #: MD1614 Long Reach Village Center - : 8775 Cloudleap Court, Columbia

Assessment Ongoing: Yes **Remediation Ongoing:** No **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: Fact Sheet Not Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1552 Grandfather's Garden Center - Grandfather's Nursery, Grandfather's Gardens: 5320 Phelps Luck Drive, Columbia

The Ryland Group, Inc., 6240 Old Dobbin Lane, Suite 190, Columbia MD 21045 INCULPABLE PERSON
Lang, Miller & Associates, Inc., 5320 Phelps Luck Drive, Columbia MD 21045 RESPONSIBLE PERSON

Assessment Ongoing: Yes **Remediation Ongoing:** No **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): Yes Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1792 Meadowridge Property - Includes Cemetery Lane West (VCP): South side of Meadowridge Road and due west of Interstate 95, adjacent to 6510 Meadowridge Road, Elkridge

Assessment Ongoing: Yes **Remediation Ongoing:** No **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: Fact Sheet Not Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1534 Savage Stone Quarry Chase School Haul Project - Laurel Sand & Gravel, Inc.: South of Mission Road, Jessup

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** Yes
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: Fact sheet not available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No



Brownfield Master Inventory (BMI) Report - Active Sites, By County
July 02, 2018

Howard

BMI #: MD0305 Cemetery Lane - Includes Cemetery Lane West (VCP): South of intersection of Mayfield Road and Meadowridge Road, Elkridge

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/Cemetery_Lane.pdf

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1355 Enchanted Forest Shopping Center - : 10000-10060 Baltimore National Pike, Ellicott City

Enchanted Forest LLC, 3333 New Hyde Park Road, New Hyde Park NY 11042-0020 RESPONSIBLE PERSON

Assessment Ongoing: No **Remediation Ongoing:** Yes **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/www.mde.state.md.us/asset/s/document/Enchanted_Forest_Shopping_Center.pdf

Voluntary Cleanup Program (VCP): Yes Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD0117 W.R. Grace Washington Research Center - W.R. Grace Columbia Property: 7379 Route 32, Columbia

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/www.mde.state.md.us/asset/s/document/brownfields/WRGrace_Research_Cntr.pdf

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD0241 Long Life Treated Wood Inc. - : Dorsey Raceway Road, Dorsey

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: <http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/www.mde.state.md.us/asset/s/document/brownfields/Long-life.pdf>

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No
Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No
Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No



Brownfield Master Inventory (BMI) Report - Active Sites, By County
July 02, 2018

Howard

BMI #: MD1056 Worthington Elementary School - : 4570 Roundhill Road, Ellicott City

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1057 Carrs Mill Landfill - : Carrs Mill Road and Bushy Park Road, Lisbon

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1012 Calvert Ridge - : 7035, 7043, 7047 Calvert Drive, Elkridge

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1013 Daedalean Inc. - : 15110 Frederick Road, Woodbine

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1014 Merritt - : 9525 Berger Road, Columbia

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No



Brownfield Master Inventory (BMI) Report - Active Sites, By County
July 02, 2018

Howard

BMI #: MD1015 Rendering Plant - : Meadowridge Road; Route 100 (800 feet southwest of MD Route 103), Elkridge

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD1016 Vista Road - : 10613 Vista Road, Columbia

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD0886 Daniels Road Drum Dump - : 2090 Daniels Road, Ellicott City

Assessment Ongoing: No **Remediation Ongoing:** Yes **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: No Fact Sheet Available.

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: No

BMI #: MD0591 Daniels Quarry - : South of Daniels Road, near the top of a north-facing slope approximately ½ mile south of Daniels, within the Patapsco State Pa, Ellicott City

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** No

Withdrawn from VCP: No **Site Closed/Archived:** No

Factsheet URL: <http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/Daniels%20Quarry.pdf>

Voluntary Cleanup Program (VCP): No Fed Facility: No State Master List*: No

Groundwater Investigation Site (GWI) No Frm. Used Def. Site (FUDS): No Non-Master List*: No

Brownfield Assessment Project: No National Priority List (NPL): No Site Assessment Project: Yes



Brownfield Master Inventory (BMI) Report - Active Sites, By County
July 02, 2018

Howard

BMI #: MD0805 Former Boise Building Materials Distribution Site - Includes Annapolis Junction Town Center - Lot D; Part of Annapolis Junction Town Center; Furman Lumber Co., Golden Key Homes, K: 8960 Henkels Lane, Annapolis Junction

Boise Building Solutions Distribution, L.L.C., PO Box 50, Boise ID 83728	RESPONSIBLE PERSON
	RESPONSIBLE PERSON
Annapolis Junction Town Center, LLC, 4816 Del Ray Avenue, Bethesda MD 20814	INCULPABLE PERSON
Annapolis Junction Town Center, LLC (Lot D), 4816 Del Ray Avenue, Bethesda MD 20814	INCULPABLE PERSON
Annapolis Junction Town Center, LLC (Lot F), 4816 Del Ray Avenue, Bethesda MD 20814	INCULPABLE PERSON

Assessment Ongoing: No **Remediation Ongoing:** No **Determination Issued:** Yes
Withdrawn from VCP: No **Site Closed/Archived:** No
Factsheet URL: <http://mde.maryland.gov/programs/Land/MarylandBrownfieldVCP/Documents/Boise%20Building%20Materials.pdf>

Voluntary Cleanup Program (VCP): <u>Yes</u>	Fed Facility: <u>No</u>	State Master List*: <u>No</u>
Groundwater Investigation Site (GWI) <u>No</u>	Frm. Used Def. Site (FUDS): <u>No</u>	Non-Master List*: <u>No</u>
Brownfield Assessment Project: <u>No</u>	National Priority List (NPL): <u>No</u>	Site Assessment Project: <u>No</u>