



Maryland
Department of
the Environment

FACTS ABOUT: EPA PUBLIC RECORD UST REPORT

SUMMARY INFORMATION ON UNDERGROUND STORAGE TANKS

Public Record Posted Date: December 16, 2022

This report is compiled annually per the US Environmental Protection Agency (EPA) grant requirements for implementing the public record provision of the Energy Policy Act of 2005. The report was created per the document *Grant Guidelines To States For Implementing The Public Record Provision Of The Energy Policy Act Of 2005*, EPA 510-R-19-002, Sept. 2019.

GENERAL INFORMATION

Federally Regulated Motor Fuel and Used Oil Systems

Total Number of UST Facilities: 2,658

Total Number of USTs: 7,100

SUMMARY INFORMATION FOR ON-SITE INSPECTIONS

Number of UST Facilities Inspected: 885

Inspection Period Dates: October 1, 2021 to September 30, 2022

Percent Compliance (Technical Compliance Rate): 73%

Note: Tank, facility, and on-site inspection information is based on reports from MDE inspection staff and reports from certified UST third-party inspectors. On-site inspections measure compliance with Code of Maryland Regulations 26.10, "Oil Pollution and Tank Management," which require release detection, financial responsibility, corrosion protection, and spill/overfill prevention.

SUMMARY INFORMATION FOR RELEASES

Number of Confirmed UST Releases: 67

Release Reporting Period Dates: October 1, 2021 to September 30, 2022



SUMMARY INFORMATION FOR RELEASE SOURCES AND CAUSES

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown*	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	12	18.5	1	1.5	0	0	0	0	7	11	0	0	0	0	4	6
Piping	10	15.5	0	0	0	0	1	1.5	0	0	0	0	2	3	7	11
Dispenser	4	6	0	0	0	0	2	3	0	0	0	0	0	0	2	3
STP	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	3	4.5	1	1.5	1	1.5	0	0	0	0	0	0	1	1.5	0	0
Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Unknown*	36	55.5	0	0	0	0	0	0	1	1.5	0	0	0	0	35	54
Totals	65**	100	2	3	1	1.5	3	4.5	8	12.5	0	0	3	4.5	48	74

= number, % = percent of total number, STP = Submersible Turbine Pump Area

Note: Release source and cause information is based on federally regulated tanks. Source and cause data were collected using the best available information from MDE inspection staff, owners, operators, certified installers/inspectors, and consultants.

* To the best of their ability, owners, operators, certified installers/inspectors, and consultants report the source of the release. However, in most instances, the exact source and cause of the release is not able to be determined.

** Sites that a conclusion on release source has been determined. Not all sites reported to EPA as confirmed releases are included in this summary.

ADDITIONAL INFORMATION

Additional information may be obtained from the Maryland Department of Environment's Oil Control Program at 410-537-3442.